Quality Control Report



Consultant	Wahib Medanat Consultant Engineers	Re
Site Name	Jumana Bint Abi Taleb Basic Mixed - Marka	D
Package	Package 2	
Contractor	Dijlah Est. Construction Co.	
Tender No.	10/2019/USAID/SKEP/3/2	

Rep No.	QC-23	03	
Date	15	/ 03 /	2021

Description of Non Conformance	Corrective Action	Required by / When
 Roughness in some areas in base course. 	1. To be remeded.	Contractor/Immediately
2. Corners of external columns are damaged.	 To be repaired by approved materials. 	Contractor/Immediately
3. Steel reinforcement has a brown layer on the face due to weather effect.	3. Need to be brush-cleaned.	Contractor/Immediately
4. Part of the imported building stone does not comply with approved sample.	4. To be removed outside the site and replaced by complied stones.	Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	

Contractor's Response

Sample was sent to the lab and the result is awaited. Sieve analysis will be considered to decide.	
Notes	

Quality Control Report





Schools for Knowledge Economy Project SKEP III

Quality Control Report





Schools for Knowledge Economy Project SKEP III

Quality Control Report





Quality Control Report



